

Insulating boots are available for most bus and cable connections in GE Magneblast switchgear. Save the time and expense of taping primary bolted connections by using insulating boots that have been specifically designed for the exact connections in your switchgear. Talk to us about your requirements.

